

00684.003290.



Copie
PATENT
S

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:

TAKASHI MORIYAMA ET AL.

Appln. No.: 09/996,883

Filed: November 30, 2001

For: ORGANIC ELECTROLUMINESCENCE
DEVICE

U.S. Patent No.: 6,908,694 B2

Issued: June 21, 2005

)
: Examiner: C.S. Thompson
)
: Group Art Unit: 1774
)
:
)
:
)
:
)
:
)

: July 24, 2006

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

*Certificate
JUL 28 2006
of Correction*

CERTIFICATE OF CORRECTION
UNDER RULES 322 AND 323

07/27/2006 HAL111 00000027 6908694

100.00 OP

01 FC:1811

Sir:


It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

AUG 01 2006

Patentees' undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,



Frank A. DeLucia
Attorney for Patentees
Registration No. 42,476

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200

NY_Main 541637v1

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,908,694 B2

DATED : June 21, 2005

INVENTOR(S) : TAKASHI MORIYAMA ET AL.

Page 1 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON THE TITLE PAGE [56] REFERENCES CITED:

Foreign Patent Documents, "JP 07-169567 * 7/1995" should be deleted.

ON THE TITLE PAGE [57] ABSTRACT:

Line 9, "last" should read --least--.

COLUMN 1:

Line 20, "he" should read --the-- and
"self-emissin" should read --self-emission--;
Line 30, "has" should read --has been--; and
Line 37, "respectively" should be deleted.

COLUMN 2:

Line 6, "effects" should read --affects--;
Line 24, "2 at" should read --2, at--; and
Line 60, "to" should read --or--.

COLUMN 3:

Line 56, "that" should be deleted; and
Line 57, "th" should read --the--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,908,694 B2

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

NY_Main 541637v1



AUG 01 2006

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,908,694 B2

DATED : June 21, 2005

INVENTOR(S) : TAKASHI MORIYAMA ET AL.

Page 2 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 4:

Line 28, "present" should read --prevent--;

Line 29, "performances" should read --performance--; and

Line 53, "performances" should read --performance--.

COLUMN 5:

Line 27, "material." should read --material is formed; and--

Line 42, "o" should be deleted.

COLUMN 6:

Line 3, "ally," should read --alloy,--;

Line 48, "pixels" should read --pixels,--; and

Line 51, "Examples" should read --examples--.

COLUMN 7:

Line 18, "by" (second occurrence) should read --is formed by--;

Line 48, "by" should read --is formed by--; and

Line 66, "by" should read --is formed by--.

COLUMN 8:

Line 34, "deice" should read --device--;

Line 52, "((100" should read --(100--; and


Line 65, "half-lie" should read --half-life--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,908,694 B2

No. of add'l. copies
@ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,908,694 B2

DATED : June 21, 2005

INVENTOR(S) : TAKASHI MORIYAMA ET AL.

Page 3 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 10:

Line 38, "include" should read --includes--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,908,694 B2

No. of add'l. copies
@ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,908,694 B2

DATED : June 21, 2005

INVENTOR(S) : TAKASHI MORIYAMA ET AL.

Page 1 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON THE TITLE PAGE [56] REFERENCES CITED:

Foreign Patent Documents, "JP 07-169567 * 7/1995" should be deleted.

ON THE TITLE PAGE [57] ABSTRACT:

Line 9, "last" should read --least--.

COLUMN 1:

Line 20, "he" should read --the-- and
"self-emissin" should read --self-emission--;
Line 30, "has" should read --has been--; and
Line 37, "respectively" should be deleted.

COLUMN 2:

Line 6, "effects" should read --affects--;
Line 24, "2 at" should read --2, at--; and
Line 60, "to" should read --or--.

COLUMN 3:

Line 56, "that" should be deleted; and
Line 57, "th" should read --the--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,908,694 B2

No. of add'l. copies
@ 30¢ per page

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

Staple
Here
Only!

PRINTER'S TRIM LINE

PATENT NO. : US 6,908,694 B2

DATED : June 21, 2005

INVENTOR(S) : TAKASHI MORIYAMA ET AL.

Page 2 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 4:

Line 28, "present" should read --prevent--;

Line 29, "performances" should read --performance--; and

Line 53, "performances" should read --performance--.

COLUMN 5:

Line 27, "material." should read --material is formed; and--

Line 42, "o" should be deleted.

COLUMN 6:

Line 3, "ally," should read --alloy,--;

Line 48, "pixels" should read --pixels,--; and

Line 51, "Examples" should read --examples--.

COLUMN 7:

Line 18, "by" (second occurrence) should read --is formed by--;

Line 48, "by" should read --is formed by--; and

Line 66, "by" should read --is formed by--.

COLUMN 8:

Line 34, "deice" should read --device--;

Line 52, "((100" should read --(100--; and

Line 65, "half-lie" should read --half-life--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,908,694 B2

No. of add'l. copies
@ 30¢ per page

Staple
Here
Only!

PRINTER'S TRIM LINE'

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,908,694 B2

DATED : June 21, 2005

INVENTOR(S) : TAKASHI MORIYAMA ET AL.

Page 3 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 10:

Line 38, "include" should read --includes--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,908,694 B2

No. of add'l. copies
@ 30¢ per page

